

Vehicle diagnostic report



Shop Name:
Address:
Telephone:
Email:

Make: Mercedes
Model: 212.003 - E 250 CDI
Year:
VIN: WDD2120031A022690
ODO: 324519km
Vehicle Software Version: V48.90
Diagnostic Application Version: 3.12.003 AG
Test Time: 2018-10-03 19:33:17
Diagnostic path: Automatically Search



Diagnostic Result

Fault (13)

TCM - Transmission Control Module	(1)	Abnormal
	0730 The transmission has an impermissible transmission ratio.	STORED
Driver-side SAM - Front signal acquisition and actuation module(N10/1)	(2)	Abnormal
	B107A11 The refrigerant pressure sensor has a malfunction. There is a short circuit to ground.	STORED
	U115100 Communication with switch group "Warning system" has a malfunction._	STORED
EZS - Electronic ignition lock(N73)	(2)	Abnormal
	A25407 The electric steering lock has a malfunction. There is a mechanical fault.	Stored
	A25464 The electric steering lock has a malfunction. There is an implausible signal.	Stored
XALWA_L - Left xenon headlamp(E1n1)	(2)	Abnormal
	9062 No CAN message was received from control unit "Steering column module".	STORED
	9068 No CAN message was received from control unit "Steering column module".	STORED
XALWA_R - Right xenon headlamp(E2n1)	(2)	Abnormal
	9062 No CAN message was received from control unit "Steering column module".	STORED

	9068 No CAN message was received from control unit "Steering column module".	STORED
RevETR_LF - Left front reversible emergency tensioning retractor(A76)	(4)	Abnormal
	530a00	STORED
	520501 The CAN message from control unit "Central gateway" is faulty.	STORED
	600608 Control unit "A76 (Left front reversible emergency tensioning retractor)" is defective.	STORED
	520400 No CAN message was received from control unit "Central gateway".	STORED
RevETR_RF - Right front reversible emergency tensioning retractor(A76/1)	(3)	Abnormal
	530a00 Multifunction output 5 has a malfunction.	STORED
	600608 Control unit "A76/1 (Right front reversible emergency tensioning retractor)" is defective.	STORED
	520400 No CAN message was received from control unit "Central gateway".	STORED
MFK - Multifunction camera(A40/11)	(1)	Abnormal
	c21287 Communication with the steering column module has a malfunction.	STORED
IC - Instrument cluster(A1)	(1)	Abnormal
	U021287 Communication with the steering column module has a malfunction.The message is missing.	STORED
SCCM - Steering column module(N80)	(1)	Abnormal
	U100800 LIN bus 1 has a malfunction._	STORED
Audio/COMAND - Audio or COMAND(A2-A2/56-A40/3)	(1)	Abnormal
	1614 An internal control unit reset was performed.	STORED
DCU_LF - Left front door(N69/1)	(3)	Abnormal
	9df701 The mirror glass sensor for the horizontal position has a malfunction.There is a general electrical fault.	STORED
	9df301 The mirror glass sensor for the vertical position has a malfunction.There is a general electrical fault.	STORED
	d13700 Communication with switch group "Seat adjustment" has a malfunction._	CURRENT and STORED
AC - Air Conditioning(N22/7)	(2)	Abnormal
	90b349 Electric heater booster 1 has a malfunction.There is an internal electrical fault.	STORED
	911315 Temperature sensor "Right footwell vent" has a malfunction.There is a short circuit to positive or an open circuit.	STORED
Normal (13)		

ECM - Engine Control Module(CDID2/CDID3) for combustion engine 'OM651'(N3/9)

Normal

SGR - Radar sensors control unit(N62/2)	Normal
ESM[EWM] - Electronic selector module(N15/5)	Normal
ESP(R) - Electronic stability program(N30/4)	Normal
CGW[ZGW] - Central gateway(CGW[ZGW])	Normal
Rear SAM - Rear signal acquisition and actuation module(N10/2)	Normal
SRS - Supplemental restraint system(N2/10)	Normal
PTS - PARKTRONIC(N62)	Normal
ZAN - Audio/COMAND display(A40/8)	Normal
COU[ZBE] - Audio/COMAND operating unit	Normal
DCU_RF - Right front door(N69/2)	Normal
DCU_LR - Left rear door(N69/3)	Normal
DCU_RR - Right rear door(N69/4)	Normal