

**Vehicle Master Inquiry (VMI)
FOR INTERNAL USE ONLY**

Option	Description	Option	Description
841	Laminated safety glass for fro	845	Electrically folding 3rd seat
846	Aluminium-look running boards	864	Rear Seat Entertainment System
872	Heated rear seats	876	ambient lighting
883	Closing aid for doors and lugg	888	Lockable load compartment floo
889	KEYLESS-GO	890	EASY-PACK tailgate
986	ID no. (VIN no.)	989	Identification label under win

Service Packages

Type	Code	Start Date	End Date	Miles Fm	Miles To	DLR or GEN	Contract #	Cust. Name
MNT	STAR MNT50K PFMS-5YR - 50,000 MILE PREPAID MAINTEN 2-R02R99	07/22/2013	04/22/2015	0	999,999		160 1 4 3 5	Name is not available
MBR	MBRACE VARIABLE MONT	07/22/2013	07/23/2015	0	999,999		1-1435299	
MBR	CONCIERGE 3 MOO7/22/2013 TRIAL	07/22/2013	10/22/2013	0	999,999		1-1435334	
MBR	mbrace Trial, 07/23/2013 New Ve	07/23/2013	01/23/2014	0	999,999		1-1445314	
MBR	mbrace Plus, 04/22/2015 Month-	04/22/2015	05/08/2015	0	999,999		1-9050142	
MBR	MBRACE PLUS 1YR	05/07/2015	01/01/2099	0	999,999		1-9125351	
MBR	mbrace 1YR	07/23/2015	01/01/2099	0	999,999		1-9347998	
MBFS	PAINTLESS REPAIR	07/19/2013	07/19/2018	0	999,999		0014321294	
MBFS	PLUS WHEEL & TIRE	07/19/2013	07/19/2018	0	999,999		0014321293	

Vehicle History

Damage Code	Damage Text	Dealer Code	RO No	Line No	Claim No	Repair Date	Miles	Service Type	Seq No
0 54897 73 7	Driver assistance package/rada	80111	102528	4	60456914	2016/05/19	42,759	03-Warranty	0003
0 21763 00 7	MNT-Star Service PPMS-40,000 K	80111	102528	1	60456914	2016/05/19	42,759	07-ISP	0001
0 50001 04 7	Radiator Leaks	80111	102528	B	60447792	2016/05/19	42,759	03-Warranty	0001
0 59120 74 7	K/Z*, fill level sensor, fuel	80111	102528	2	60456914	2016/05/19	42,759	03-Warranty	0002
0 21762 00 7	MNT-Star Service PPMS-30,000 K	80111	83982	1	58114993	2015/06/03	30,949	07-ISP	0001
0 91A0H 04 8	Air cushion, upper leg area, s	80111	83982	3	58114993	2015/06/03	30,949	03-Warranty	0002
0 68286 38 7	Insert, ashtray/stowage box Lo	80111	73881	4	56966755	2014/12/08	23,794	03-Warranty	0001
0 21761 00 7	MNT-Star Service PPMS-20,000 S	80111	69823	1	56470310	2014/09/27	20,534	07-ISP	0001
0 42101 H4 7	Brake disc, front Jerks	80111	69823	4	56470310	2014/09/27	20,534	03-Warranty	0002
0 53V00 F1 8	Screen, right, rear Variant co	80111	59144	3	55249137	2014/03/06	9,982	03-Warranty	0002

**Vehicle Master Inquiry (VMI)
FOR INTERNAL USE ONLY**

Damage Code	Damage Text	Dealer Code	RO No	Line No	Claim No	Repair Date	Miles	Service Type	Seq No
0 21760 00 7	MNT-Star Service PPMS- 10,000	80111	59144	1	55249137	2014/03/06	9,982	07-ISP	0001
0 88506 38 8	Holder, front camera Loose	80111	47552	6	53999669	2013/08/08	811	03-Warranty	0001
0 91N15 07 7	Cover, backrest front right To	80111	47552	1	53991833	2013/08/08	811	03-Warranty	0001
0 53V00 52 7	Screen, right, rear Does not o	80111	47552	3	53991833	2013/08/08	811	03-Warranty	0003
0 82N46 73 7	Head restraint adjustment moto	80111	47552	5	53991833	2013/08/08	811	03-Warranty	0004
0 91N32 26 7	Cover, head restraint, seat fr	80111	47552	2	53991833	2013/08/08	811	03-Warranty	0002
1 21852 ZZ 0	Dealer Pre- Delivery (PDI)	80111	102544	A	53940894	2013/07/31		RAPS	0001
0 82876 54 8	Control unit, emergency call s	80111	47498	5	53913555	2013/07/25	5	03-Warranty	0001

Customer Pay Data

Dealer Code	RO Number	Repair Date	RO Mileage	TIS	OP Code/Part #	Description
80111	113606	12/27/2016	48,400	000	009	Complete alignment
80111	113606	12/27/2016	48,400	000	039	Cpo inspect report
80111	113606	12/27/2016	48,400	000	042	Repl wiper insert (s)
80111	113606	12/27/2016	48,400	000	071	Paint and cosmetic
80111	113606	12/27/2016	48,400	000	098	Out mileage
80111	113606	12/27/2016	48,400	000	098	Dent repairs sublet
80111	113606	12/27/2016	48,400	000	098	M/gl v6 1/3/5/7/9-
80111	113606	12/27/2016	48,400	000	A1668201045 28	Ts wiper blade
80111	113606	12/27/2016	48,400	000	A1668300218	Dust filter
80111	113606	12/27/2016	48,400	000	A1698201745	Wiper blade
80111	113606	12/27/2016	48,400	000	A2761800009	Ts oil filter element
80111	113606	12/27/2016	48,400	000	N007603012102	Ring,general,metal
80111	113471	12/21/2016	48,341	000	008	Emissions inspection
80111	113471	12/21/2016	48,341	000	039	Va state inspection
80111	113471	12/21/2016	48,341	000	039	Cert preowned insp
80111	113471	12/21/2016	48,341	000	072	Full detail
80111	113471	12/21/2016	48,341	000	098	Out mileage
80111	111017	11/10/2016	47,576	000	020	Sublet
80111	111017	11/10/2016	47,576	000	057	Tire pressure light
80111	111017	11/10/2016	47,576	000	057	Body electrical
80111	111017	11/10/2016	47,576	000	071	Paint and cosmetic
80111	111017	11/10/2016	47,576	000	072	Interior trim
80111	111017	11/10/2016	47,576	000	072	Misc interior trim
80111	111017	11/10/2016	47,576	000	073	Loaner car
80111	111017	11/10/2016	47,576	000	097	Multi-point inspect
80111	111017	11/10/2016	47,576	000	098	Out mileage
80111	111017	11/10/2016	47,576	000	098	*** opcode not on report ***

**Vehicle Master Inquiry (VMI)
FOR INTERNAL USE ONLY**

Dealer Code	RO Number	Repair Date	RO Mileage	TIS	OP Code/Part #	Description
80111	111017	11/10/2016	47,576	000	A0008206851	Socket-outlet
80111	111017	11/10/2016	47,576	000	N000000007651	Fuse link
80111	102528	05/31/2016	42,691	000	007	Rotate tires
80111	102528	05/31/2016	42,691	000	009	Complete alignment
80111	102528	05/31/2016	42,691	000	039	Va state inspection
80111	102528	05/31/2016	42,691	000	055	Red tire
80111	102528	05/31/2016	42,691	000	072	Full detail
80111	102528	05/31/2016	42,691	000	073	Loaner car
80111	102528	05/31/2016	42,691	000	097	Multi-point inspect
80111	102528	05/31/2016	42,691	000	098	Out mileage
80111	102528	05/31/2016	42,691	000	BQ8400562	Tire, continental 295/40r
80111	83982	06/04/2015	30,941	000	008	Emissions inspection
80111	83982	06/04/2015	30,941	000	013	Repl r/discs & pads
80111	83982	06/04/2015	30,941	000	056	Tires/ r&b
80111	83982	06/04/2015	30,941	000	057	Body electrical
80111	83982	06/04/2015	30,941	000	072	Full detail
80111	83982	06/04/2015	30,941	000	073	Loaner car
80111	83982	06/04/2015	30,941	000	097	Multi-point inspect
80111	83982	06/04/2015	30,941	000	098	Out mileage
80111	83982	06/04/2015	30,941	000	A0019899451	Brake paste
80111	83982	06/04/2015	30,941	000	A0074207820	Ts disk brake pad
80111	83982	06/04/2015	30,941	000	A1664230212	Brake disk, vented
80111	83982	06/04/2015	30,941	000	A2115401717	Brake wear sensor
80111	83982	06/04/2015	30,941	000	A2204210171	Pan head fit bolt
80111	83982	06/04/2015	30,941	000	N000000007651	Fuse link
80111	73881	12/10/2014	23,789	000	009	Complete alignment
80111	73881	12/10/2014	23,789	000	009	Free alignment check
80111	73881	12/10/2014	23,789	000	042	Repl wiper insert (s)
80111	73881	12/10/2014	23,789	000	056	Mount new tires
80111	73881	12/10/2014	23,789	000	072	Full detail
80111	73881	12/10/2014	23,789	000	097	Multi-point inspect
80111	73881	12/10/2014	23,789	000	098	Out mileage
80111	73881	12/10/2014	23,789	000	A1668201045	Ts wiper blade
80111	73881	12/10/2014	23,789	000	A1698201745	Wiper blade
80111	73881	12/10/2014	23,789	000	BQ8400562	Tire, continental 295/40r
80111	69823	09/30/2014	20,525	000	008	Emissions inspection
80111	69823	09/30/2014	20,525	000	009	Free alignment check
80111	69823	09/30/2014	20,525	000	039	Va state inspection
80111	69823	09/30/2014	20,525	000	055	Repair leak in tire
80111	69823	09/30/2014	20,525	000	073	Loaner car
80111	69823	09/30/2014	20,525	000	097	Multi-point inspect
80111	69823	09/30/2014	20,525	000	098	Out mileage
80111	59144	03/07/2014	9,982	000	009	Free alignment check
80111	59144	03/07/2014	9,982	000	072	Full detail
80111	59144	03/07/2014	9,982	000	073	Loaner car
80111	59144	03/07/2014	9,982	000	097	Multi-point inspect
80111	59144	03/07/2014	9,982	000	098	Out mileage
80111	47552	08/08/2013	811	000	098	Out mileage

**Vehicle Master Inquiry (VMI)
FOR INTERNAL USE ONLY**

Dealer Code	RO Number	Repair Date	RO Mileage	TIS	OP Code/Part #	Description
80111	47759	07/25/2013	387	000	071	Paint and cosmetic
80111	47759	07/25/2013	387	000	088	Fab protection
80111	47759	07/25/2013	387	000	097	Multi-point inspect
80111	47759	07/25/2013	387	000	098	Out mileage
80111	47759	07/25/2013	387	000	098	Clean-up instruct
80111	47498	07/25/2013	5	000	0S1	Va state inspection
80111	47498	07/25/2013	5	000	038	Pdi
80111	47498	07/25/2013	5	000	088	New car paint seal
80111	47498	07/25/2013	5	000	098	Esn number