

Inspection Report

This report is created by

LAUNCH

Vehicle Information

VIN: WDC0G4KB2JV*****

Vehicle manufacturer/model: Mercedes/GLC

Year of manufacture: 2018

Mileage: 49236

Vehicle Software Version: V49.86

Inspection Organization

Name:

Address:

Contact Number: 

SN: 960744003988

Time and date of inspection: 09/08/2022 01:12:51

Inspection Location: 

Inspection Result

There are 4 issues for Power system:

- 1.Communication with the instrument cluster has a malfunction.The message is missing.
- 2.Communication with the central gateway has a malfunction._
- 3.Communication with the steering column module has a malfunction._
- 4.Communication with the instrument cluster has a malfunction.The signal is not present.

There are 1 issues for Safety and Security system:

- 1.There is a warning from the control unit "COLLISION PREVENTION ASSIST"._

There are 5 issues for Vehicle body system:

- 1.Control unit 'LED driving lights actuation module' has a malfunction.The message is missing.
- 2.The starter battery has excessive resistance._
- 3.The rain sensor has a malfunction.There is a fault due to overtemperature.
- 4.Communication with the electronic ignition lock has a malfunction.The message is missing.
- 5.Control unit 'LED driving lights actuation module' has a malfunction.The message is missing.

Inspections are normal for Power system

- 1.ECM - Engine Control Module(ME)
- 2.FSCU - Fuel Pump

Inspections are normal for Chassis system

- 1.TPM - Tire Pressure Monitor

Inspections are normal for Safety and Security system

- 1.PTS - PARKTRONIC
- 2.RevETR_LF - Left Front Reversible Emergency Tensioning Retractor
- 3.ES - Electrical Power Steering
- 4.IRS-HRA - Outer Right Rear Intelligent Radar Sensor System
- 5.RevETR_RF - Right Front Reversible Emergency Tensioning Retractor
- 6.ESP - Electronic Stability Program
- 7.IRS-HLA - Outer Left Rear Intelligent Radar Sensor System
- 8.SCM - Steering Column Module
- 9.KAB - Camera Cover
- 10.SRS - Supplemental Restraint System

Inspections are normal for Vehicle body system

- 1.COUP[ZBE] - Audio/COMAND Operating Unit
- 2.Control unit for telematics services
- 3.360 Degree Camera - 360 Degree Camera
- 4.IC - Instrument Cluster
- 5.AC - Air Conditioning
- 6.DCU_LF - Left Front Door
- 7.DCU_RF - Right Front Door
- 8.DCU_LR - Left Rear Door
- 9.EZS - Electronic Ignition Lock
- 10.REAR SAM - Rear Signal Acquisition And Actuation Module
- 11.KG - KEYLESS GO
- 12.HKS - Tailgate Control
- 13.ESA_DR - Electric Seat Adjustment Driver
- 14.DCU_RR - Right Rear Door

Inspections are normal for Infotainment system

- 1.ZAN - Audio/COMAND Display
- 2.TV - TV Tuner
- 3.TPAD - Touchpad
- 4.Audio - Audio Or COMAND
- 5.SOUND - Sound System

Professional Report

PTS - PARKTRONIC	Normal ▼
ECM - Engine Control Module(ME)	Normal ▼
SG-SW_R - Right Headlamp	Abnormal 1 ▼
Driver-side SAM - Front Signal Acquisition And Actuation Module	Abnormal 2 ▼

RevETR_LF - Left Front Reversible Emergency Tensioning Retractor	Normal	▼
ZAN - Audio/COMAND Display	Normal	▼
SG-AWF - COLLISION PREVENTION ASSIST	Abnormal	1 ▼
TV - TV Tuner	Normal	▼
COU[ZBE] - Audio/COMAND Operating Unit	Normal	▼
ES - Electrical Power Steering	Normal	▼
SD - Control Module Sliding Roof	Abnormal	1 ▼
IRS-HRA - Outer Right Rear Intelligent Radar Sensor System	Normal	▼
PTCU - Drivetrain	Abnormal	1 ▼
TCM - Transmission Control Module	Abnormal	3 ▼
RevETR_RF - Right Front Reversible Emergency Tensioning Retractor	Normal	▼
TPAD - Touchpad	Normal	▼
Audio - Audio Or COMAND	Normal	▼
Control unit for telematics services	Normal	▼
ESP - Electronic Stability Program	Normal	▼
FSCU - Fuel Pump	Normal	▼
TPM - Tire Pressure Monitor	Normal	▼
360 Degree Camera - 360 Degree Camera	Normal	▼
IRS-HLA - Outer Left Rear Intelligent Radar Sensor System	Normal	▼
SCM - Steering Column Module	Normal	▼
SG-SW_L - Left Headlamp	Abnormal	1 ▼
KAB - Camera Cover	Normal	▼

IC - Instrument Cluster	Normal ▾
AC - Air Conditioning	Normal ▾
DCU_LF - Left Front Door	Normal ▾
DCU_RF - Right Front Door	Normal ▾
DCU_LR - Left Rear Door	Normal ▾
EZS - Electronic Ignition Lock	Normal ▾
REAR SAM - Rear Signal Acquisition And Actuation Module	Normal ▾
KG - KEYLESS GO	Normal ▾
SRS - Supplemental Restraint System	Normal ▾
SOUND - Sound System	Normal ▾
HKS - Tailgate Control	Normal ▾
ESA_DR - Electric Seat Adjustment Driver	Normal ▾
DCU_RR - Right Rear Door	Normal ▾

Disclaimer

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.