


2013 MERCEDES-BENZ GLK-Class

WDCGG5HB3DG123358





Last Entered Odometer: 139,267 mi

 Smog Readiness Check Failed
Address issues below before Smog Check








Smog Readiness Status

Check Engine Light is On		1 Pending Trouble Codes	
1 Confirmed Trouble Codes			

Common I/M Monitors

Misfire Test is complete		Fuel System Test is complete	
Comprehensive Component Test is complete		EGR and/or VVT System Test is complete	

Spark Engine I/M Monitors

Catalyst Test is complete		Heated Catalyst Test is not applicable	
Evaporative System Test is complete		Secondary Air System Test is not applicable	
A/C Refrigerant Test is not applicable		Oxygen Sensor Test is NOT complete	
Oxygen Sensor Heater Test is complete			

Disclaimer: This information is provided without warranty and is subject to the Terms of Use posted at www.bluedriver.com/eula.html. Reproduction of this information or any portion thereof constitutes infringement of copyright.