

## Vehicle Information

Brand: MERCEDES	VIN: WDCGG0EBXEG317006	Plate Number:
Model: 204.904	Mileage: 303630 km	Color:
Year:	Capacity:	Status: Unset status
Engine: 651.912	Reference:	Date: 09.07.2024 23:51:24

## Read codes

Name	Status	Description
<a href="#">P261F00</a>	Stored	The output for the circulation pump 'Coolant' has a malfunction or does not switch on.
<a href="#">P2D2F00</a>	Stored	Please refer to vehicle service manual!
<a href="#">P00C400</a>	Stored	The output for the switchover valve of bypass flap 2 'Charge air' has a mechanical malfunction.
<a href="#">P0299FA</a>	Stored	The boost pressure of turbocharger 1 is too low.
<a href="#">P0299FE</a>	Stored	Please refer to vehicle service manual!
<a href="#">P056EFA</a>	Stored	Please refer to vehicle service manual!
<a href="#">P245B00</a>	Stored	The switchover valve for bypass 'Exhaust gas recirculation cooler' has a malfunction.
<a href="#">P245B09</a>	Stored	Please refer to vehicle service manual!

## Contact Information

Name: Jeremy Ocampo

Address: 98801

---

Phone:

Email:

Website:

---

APP Version: V1.21.004