


i Shown with tilting/sliding roof cover removed

- 1 Check position of hole (1) in upper gate, in relation to drive wedge (2) in lower gate.
i Distance of hole (1) to drive wedge (2) max. 3 mm, deviation from left to right side of vehicle, approx. 2 mm.



P77.20-2609-01