

Repair Order Detail - Internal Copy

RO Number: 228385

RO Status: CLOSED

Customer: CORNEJO,STEVE
Phone(s): Contact: (909)900-7420
Vehicle: WDDNG77X08A153714

Main: (909)900-7420
2008 S63AMG BLACK

[Click to View Cust Copy](#)
Cell: (909)900-7420
7ELG259

Mileage: 90,464
Service advisor: 167
Tag number: T3667

Payment type: CASH
Promised time: 04:00 PM
Promised date: 07/09/2015

Waiter: No
Estimate: 0.00
Customer Comments: No

~~~~~  
A CLIENT REQUESTS TO DOUBLE CHECK ALL THE SERVICES THAT WERE PERFORMED ON RO#227190. CLIENT FOUND VARIOUS FLUID LEVELS LOW.PLEASE CHECK AND ADVISE  
NOTE IPS SEE STORY 0.00 0.00  
Tech(s): 271  
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line A: 0.00  
Story: 90467 RECHECK ALL FLUID LEVEL \*\*CHECK ALL FLUIDS LEVEL, VEHICLE HAS OIL LEAK FROM UNDER ENGINE, OIL CAP WORN (LEAKING OIL) CLIENT DECLINED WORK LAST VISIT. COOLANT LEVEL AT FILLING MARK. WE CAN NOT FILL PASS MARK WILL RESULT COOLANT LEAK AT VENT. TECH 271  
~~~~~

B SHOP FOREMAN QUALITY CONTROL INSPECTION RESULTS AND NOTES ARE AS FOLLOWS:
12 IPS SHOP FOREMAN QUALITY CONTROL INSPECTION RESULTS AND NOTES ARE AS FOLLOWS: 0.00 0.00
Tech(s): 999
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line B: 0.00
Story: 90467 inspected car for low windshield washer fluid level it was just below the filler neck, checked engine oil level was half quart low added half quart oil, coolant level was ok. 07/09/2015.
~~~~~

C Perform California state COLD tire inflation check and correction as mandated by state law AB32  
PSI IPS Perform California state COLD tire inflation check and correction as mandated by state law AB32 0.00 0.00  
Tech(s): 271  
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line C: 0.00  
Story: 90467 \*\*CORRECT TIRES PRESSURE, FRONTS 38PSI, REARS 38PSI, FRONT TIRES 7MM, REARS 6MM, TECH 271  
~~~~~

D CAR WASH
CW IPS CAR WASH 0.00 0.00
Tech(s): 999
Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line D: 0.00
~~~~~

E VEHICLE WAS PICKED UP BY CHRISTINA ROSS  
MISC IPS MISC 0.00 0.00

# Repair Order Detail - Internal Copy

RO Number: 228385

RO Status: CLOSED

Customer: CORNEJO,STEVE

[Click to View Cust Copy](#)

Phone(s): Contact: (909)900-7420

Main: (909)900-7420

Cell: (909)900-7420

Vehicle: WDDNG77X08A153714

2008 S63AMG

BLACK

7ELG259

Mileage: 90,464

Payment type: CASH

Waiter: No

Service advisor: 167

Promised time: 04:00 PM

Estimate: 0.00

Tag number: T3667

Promised date: 07/09/2015

Customer Comments: No

~~~~~  
Tech(s): 999

Pts: 0.00 Lbr: 0.00 Other: 0.00 Total Line E: 0.00
~~~~~

|                           |      |
|---------------------------|------|
| Customer Pay              |      |
| Labor                     | 0.00 |
| Parts                     | 0.00 |
| Lube                      | 0.00 |
| Sublet                    | 0.00 |
| Miscellaneous/Shop Charge | 0.00 |
| Deductible                | 0.00 |
| Total Charges             | 0.00 |
| Less Insurance/Adjustment | 0.00 |
| Sales Tax                 | 0.00 |
| Total                     | 0.00 |