18MAR11 DD		110.00	CASH	04NOV14
R.O. OPENED READY OPTIONS:				
270CT14 04NOV14				
LINE OPCODE TECH TYPE HOURS		TTOM	NET	
9 000-989-83-01-USB6 MB GENUIN	E ENGINE OIL	LIST	NET	TOTAL
5W-40 MB 229.5		9.30	9.30	02 70
1 000-989-25-45-16 FUEL ADDITIVE		16.80		
1 001-986-80-71-17 WINDSHIELD WASHER FLUITD		4.20		A CONTRACTOR OF THE PARTY OF TH
44513 3.00 PERFORMED "B" SERVICE				7.20
***********	******	*****	***	
D CUST STATESW POPPING NOISE SOUNDS LIN	KE IT IS COMING	FROM DRI	VER SIDE	
ROOF TRIM				
O PERFORMED TEST DRIVE WITH CUSTON	MER AND COULD			
NOT REPRODUCE SOUND 178 CM				
			0.00	0.00
44513 PERFORMED TEST DRIVE WITH CUSTON SOUNDS	MER AND COULD NO	T PRODUC	E	
************	****	***		
E CUST STATES INSIDE OF HEADLAMP LENS H	ADC MADK OD COMP	ENCARTON	***	
NEVER GOES AWAY	IAD MARK OR COND	ENSALION	THAT	
CAUSE: F				
824810 FRONT LAMP UNITS (BOTH) REP	PLACE			
178 WM08 824889 EXTRA WORK FOR: LAMP UNITS (BOTH) AT FRONT				(N/C)
				(=:/ =/
REPLACE VEH. WITH XENON HEADLAMPS 178 WM08				
1 212-820-11-39 HEADLAMP UNIT				(N/C)
1 212-820-11-39 HEADLAMP UNIT				(N/C)
44513 D.C.82A18097 (BOTH FRONT HEADLIGHTS HAVE A "V" ETCHED IN THEM)				(N/C)
1.70 82-4810 1.40 Front lamp units (both) Replace) 82-4889 .30 Extra				
WOLK TOI: Dally utills (DOIN) at front Replace Web with women hards				
	· * * * * * * * * * * * * * * * * * * *	*****	readramps	
F CUST STATES BUTTON FOR DRIVER DOOR UN	LOCK IS PEELING			
CAUSE: F				
802024 SWITCH FOR CENTRAL LOCKING	ON DOOR PANEL,			
LOCATION: REMOVE/INSTALI	, INSPECT AND,			
IF NECESSARY, REPLACE				
	STATEMENT OF DISCLAIMER	I de la descripción de la constante de la cons		(N/C)
ON BEHALF OF SERVICING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE	The factory warranty constitutes all of the warranties with respect to the sale of this itemlitems. The Seller hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or fitness for a particular purpose. Seller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items.	DESCRI		TOTALS
		LABOR AMOU	2000 10	
VEHICLE OR CHIERWISE THAT ANY DART DEDAIDED OF DEDIAGED		GAS, OIL, LU		
UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS		SUBLET AMO		
CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVICING DEALER FOR INSPECTION BY		MISC. CHARG		
MANUFACTURER'S REPRESENTATIVE.		TOTAL CHAR		
		LESS INSURA		
(SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)		SALES TAX		
DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)		PLEASE PAY	/	
		THIS AMOU		

CUSTOMER COPY

Thank You!