

OPEN

FINGERS UNDER HERE AND PULL UP

333



THEN PULL OUT



NOTICE THE CLIPS, WHEN YOU PULL UP THEY WILL NOT BREAK

AFTER PULLING UP, YOU TILT AND PULL FORWARD



FRONT



REMOVE SCREWS



P

R

N

R
I
N
I
D

SLIDE OUT FORWARD

A 212 682 03 86
AMC





PULL OUT UNF

D
-
N
-
R

FF ELECTRONICS
800 100 1000
1000 W. 100th St.
St. Louis, MO 63104

A 212 682 03 86
Phil Data
AMC



AFTER YOU MOVE SHIFTER
YOU CAN SLIDE OUT ASH TRAY





ASH TRAY
BEING PULLED



4MG W212 2R Geh. m. Aachen
DC T₀: A 212 600 14 50
Stand: 02
Datum: 15.04.10 - 14.50

UNCLIP





CENTER OF
LIGHTER IS
USED MET
FOLLOW V
TO MAIL
CONNECT
COLOR IS
DIFEEPE

BLACK/GREEN WIRE IS 12V SWITCHED



CLOSER LOOK, DONT
USE THE OTHER THE OTHER WIR




A close-up photograph of the interior wiring of a car, specifically the area under the center console. The image shows a complex arrangement of black and white wires, a blue screw, and a metal bracket. A white label with some text is visible in the upper left corner. The background is dark and out of focus.

Wires CAN BE PUSHED THROUGH HERE
FROM LEFT OF CENTER CONSOLE
WHERE THE GAP IN THE CARPET IS
BETWEEN DRIVERS SEAT AND
CENTER CONSOLE, FOR REMOTE MUTE
SWITCH

NOTE MUTE
CH



WIDER TO MOVE THIS FORWARD
WIFE MOVES THE SEAT UP
MASSAGE SEAT CONTROLS
HIT AND RIPP OF THE SWITCH
NO AND ALL



VELCRO SUCKS
NEED TO MAKE
A CLIP BRACKET
VELCRO FOR NOW




VELCROWED

GROUND TO THIS
RIGHT IN THE MIDDLE



ALL CONNECTED




RUN WIRE UP UNDER THE
SIDE OF CENTER CONSOLE



ZIP TIE EXCESS, WILL
BE TUCKED AWAY LATER





TUCK UNDER AL THE WIRES ON THE LEFT

TUCKING
UP THE SIDE



REMOVED 3 SCREWS AND PULL DOWN





PULL WEATHER
STIPPING



RY OFF PLASTIC AIR BAG LABEL AND REMOVE SCREW ON PIL



WIRE

TUCK THE WIRE HERE



A close-up photograph of a black plastic component, likely a car's interior trim. A thin wire is tucked behind a brown plastic part on the left. A circular screw hole is visible in the black plastic. Red text is overlaid on the image.

WIRE TUCKED BEHIND BROWN BO

SCREW HOLE, SCREW IS HARD
TO PUT BACK ONLY GOES IN
A FEW TURNS

REMOVED THIS FROM CENTER OF WINDSHEID
UNDER REAR VIEW MIRROR, JUST GRAB AND PULL



A close-up photograph of a black metal grate, likely from a furnace or boiler. The grate consists of several horizontal bars. A notch has been cut into the middle bar, and a small piece of metal has been removed from the grate's surface below the notch. The background is a dark, textured surface.

I PUT A NOTCH IN MINE FOR THE WIRE



THIS FIT BETTER AFTER I
NOTCHED OUT MORE STUFF
ON THE NEXT PICTURE



ZIP TIE THE W
SO IT DOES N
GET RIPPED O
WHEN YOU R
SUCTION UPS

NOTCHED THIS OUT
WITH NEEDLE NOSE
PLIERS TO GIVE THE WIRE
MORE ROOM



DONE :D

